BROADCOM®

Product Obsolescence Notification

Issue Date: November 8, 2018

Dear **CUSTOMER**:

Broadcom Inc. regrets to announce the obsolescence of the following products:

We cannot accept new order. Please use suggested replacement.

Broadcom Part Numbers	Description	Suggested Replacement
BCM58522BA0IF10G	Integrated CPU with 2-port Eth	BCM58522BB1IF10G
BCM58522BA0KF10G	Integrated CPU with 2-port Eth	BCM58522BB1KF10G
BCM58522BB0IF12G	Dual core 1.GHz A9 SoC w/2 GPHY i-temp	BCM58522BB1IF12G
BCM58522BB0KF10G	Dual core 1GHz A9 SoC with 2 GPHYs	BCM58522BB1KF10G
BCM58522BB0KF12G	Dual core A9 SoC with 2 GPHYs	BCM58522BB1KF12G
BCM58523BB0KF12G	Dual core A9 SoC with 2 GPHYs	BCM58523BB1KF12G
BCM58525BB0IF12G	Dual core 1.2GHz A9 w/ 2GPHY	BCM58525BB1IF12G
BCM58525BB0KF10G	Dual core 1GHz A9 w/ 2GPHY	BCM58525BB1KF10G
BCM58525BB0KF12G	Dual core 1.2GHz A9 w/ 2GPHY	BCM58525BB1KF12G
BCM58535BA0KF12G	dual core Cortex-A9 with 2.5G SGMII	BCM58535BA1KF12G
BCM58535BA0KF14G	1.4GHz 2-cre Cortex-A9 with 2.5G SGMI	BCM58535BA1KF14G
BCM58622BA0KF12G	Integrated CPU with 5-port Eth	BCM58622BB1KF12G
BCM58622BB0KF12G	Dual core A9 SoC with 2 GPHYs	BCM58622BB1KF12G
BCM58625BA0IF10G	Integrated CPU with 5-port Eth	BCM58625BB1IF10G
BCM58625BA0KF12G	Integrated CPU with 5 GPHY	BCM58625BB1KF12G
BCM58625BB0IF10G	Dual core 1GHz A9 w/ 2GPHY	BCM58625BB1IF10G
BCM58625BB0KF12G	Dual core 1.2GHz A9 w/ 2GPHY	BCM58625BB1KF12G
BCM88312BB0KF12G	8-port 10/100/100	BCM88312BB1KF12LG

Please contact your Broadcom Inc. field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.