


PCN Number:	20170227000	PCN Date:	March 30, 2017
Title:	Datasheet for TPS65135		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process
Notification Details			
Description of Change:			
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.			
		TPS65135 <small>SLVS704C – NOVEMBER 2011 – REVISED JANUARY 2017</small>	
Changes from Revision B (June 2015) to Revision C			Page
<ul style="list-style-type: none"> Changed L2 pin numbers From: 1 and 14 To: 13 and 14 in the <i>Pin Functions</i> table Changed PGND pin numbers From: 11 and 11 To: 11 and 12 in the <i>Pin Functions</i> table 			3 3
The datasheet number will be changing.			
Device Family	Change From:	Change To:	
TPS65135	SLVS704B	SLVS704C	
These changes may be reviewed at the datasheet links provided. http://www.ti.com/product/TPS65135			
Reason for Change:			
To accurately reflect device characteristics.			
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):			
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.			
Changes to product identification resulting from this PCN:			
None.			
Product Affected:			
TPS65135RTER			

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com