



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M001037

DATE: 03-Jun-2021

## PRODUCT DISCONTINUANCE NOTICE

| Notice Type    | Maxim Part Number | Recommended Replacement | Last Order Date | Last Delivery Date | Reason                              |
|----------------|-------------------|-------------------------|-----------------|--------------------|-------------------------------------|
| Discontinuance | MAX2140ETH+       | MAX2142GTM/V+           | 03-Jun-2022     | 30-Nov-2022        | Part can no longer be manufactured  |
| Discontinuance | MAX2140ETH+D      | MAX2142GTM/V+           | 03-Jun-2022     | 03-Jun-2022        | Part can no longer be manufactured  |
| Discontinuance | MAX30208CLB+CTL   | MAX30208CLB+            | 03-Jun-2022     | 30-Nov-2022        | Part can no longer be manufactured  |
| Discontinuance | MAX30208CLB+TCTL  | MAX30208CLB+T           | 03-Jun-2022     | 30-Nov-2022        | Part can no longer be manufactured  |
| Discontinuance | MAX32600-J85A+    | N/A                     | 03-Jun-2022     | 30-Nov-2022        | The eval kit is no longer supported |
| Discontinuance | MAX32600-J85B+    | N/A                     | 03-Jun-2022     | 30-Nov-2022        | The eval kit is no longer supported |
| Discontinuance | MAX32600-P85B+    | N/A                     | 03-Jun-2022     | 30-Nov-2022        | The eval kit is no longer supported |
| Discontinuance | MAX32600-W00+     | N/A                     | 03-Jun-2022     | 30-Nov-2022        | The eval kit is no longer supported |
| Discontinuance | MAX32600-W00+T    | N/A                     | 03-Jun-2022     | 30-Nov-2022        | The eval kit is no longer supported |
| Discontinuance | MAX32600-W85B+    | N/A                     | 03-Jun-2022     | 30-Nov-2022        | The eval kit is no longer supported |
| Discontinuance | MAX9260GCB/V+CPT  | N/A                     | 03-Jun-2022     | 30-Nov-2022        | Part can no longer be manufactured  |
| Discontinuance | MAX9260GCB/V+TCPT | N/A                     | 03-Jun-2022     | 30-Nov-2022        | Part can no longer be manufactured  |
| Discontinuance | MAX96751GGTN/V+   | MAX96751FGTN/V+         | 03-Jun-2022     | 30-Nov-2022        | Part can no longer be manufactured  |
| Discontinuance | MAX96751GGTN/V+T  | MAX96751FGTN/V+T        | 03-Jun-2022     | 30-Nov-2022        | Part can no longer be manufactured  |
| Discontinuance | MAX96751GGTN/VY+  | MAX96751FGTN/VY+        | 03-Jun-2022     | 30-Nov-2022        | Part can no longer be manufactured  |
| Discontinuance | MAX96751GGTN/VY+T | MAX96751FGTN/VY+T       | 03-Jun-2022     | 30-Nov-2022        | Part can no longer be manufactured  |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 04-Jul-2021