



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000818

DATE: 12-Feb-2016

PRODUCT DISCONTINUANCE NOTICE

| Notice Type | Maxim Part Number | Recommended Replacement | Last Order Date | Last Delivery Date | Reason |
|----------------------|-------------------|-------------------------|-----------------|--------------------|--|
| Reactivation | DS1088CX-133+ | N/A | | | Part reactivated from prior notice: M000793 |
| Reactivation | DS1088CX-133+T | N/A | | | Part reactivated from prior notice: M000793 |
| Reactivation | DS1339C-2# | N/A | | | Part reactivated from prior notice: M000817 |
| Reactivation | DS1339C-3# | N/A | | | Part reactivated from prior notice: M000817 |
| Reactivation | MAX2180AEVKIT# | N/A | | | Part reactivated from prior notice: M000790 |
| Lead-Free Conversion | DS1856B-020 | DS1856B-020+ | 13-Aug-2016 | 11-Feb-2018 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | DS1859E-020 | DS1859E-020+ | 13-Aug-2016 | 11-Feb-2018 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX1716EEG | N/A | 13-Aug-2016 | 11-Feb-2018 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | MAX614ESA | N/A | 13-Aug-2016 | 11-Feb-2018 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | PHY1097-02DS-FR | N/A | 13-Aug-2016 | 11-Feb-2018 | Part is leaded. Request information on lead-free version |
| Lead-Free Conversion | PHY1097-02DS-WR | N/A | 13-Aug-2016 | 11-Feb-2018 | Part is leaded. Request information on lead-free version |
| Discontinuance | DS12885TN+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | DS2740EVKIT+ | DS2756EVKIT+ | 12-Feb-2016 | 12-Feb-2016 | EVKIT is No Longer Supported |
| Discontinuance | DS8313-RRX+ | DS8005-RRX+ | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | DSCIGM1-CC3+T&R | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | IC0400C778BF+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | IC0400C781SF+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | IC0400C782SF+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | IC0400K778BF+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | IC0400K782SF+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | IC0410C778BF+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | IC0410C782SF+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX1427ETN+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX14522AEWC+T | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX14522AEZC+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX14811CTN+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 14-Mar-2016

| | | | | | |
|----------------|------------------|-----------------|-------------|-------------|------------------------------------|
| Discontinuance | MAX1504ZETL+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX1543ETP+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX17141ETG+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX17205EVKIT# | MAX17205GEVKIT# | 12-Feb-2016 | 12-Feb-2016 | EVKIT is No Longer Supported |
| Discontinuance | MAX232ACPE+WCC1 | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX232ACSE+TWCC1 | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX232ACWE+TWCC1 | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX2990EVKITB# | MAX2990EVKITBC# | 12-Feb-2016 | 12-Feb-2016 | EVKIT is No Longer Supported |
| Discontinuance | MAX2990EVKITC# | MAX2990EVKITBC# | 12-Feb-2016 | 12-Feb-2016 | EVKIT is No Longer Supported |
| Discontinuance | MAX3246EEBX | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX32550-LNJ+W | MAX32550-LNJ+ | 13-Aug-2016 | 11-Feb-2018 | The part was not released |
| Discontinuance | MAX32550-LNS+W | MAX32550-LNS+ | 13-Aug-2016 | 13-Aug-2017 | The part was not released |
| Discontinuance | MAX34440ETL+ | MAX34440ETLA1+ | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX34440ETL+T | MAX34440ETLA1+T | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX34463AA00+ | MAX34463EXQA2+ | 13-Nov-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX34463AA00+T | MAX34463EXQA2+ | 13-Nov-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX35101EVKIT# | MAX35103EVKIT# | 12-Feb-2016 | 12-Feb-2016 | EVKIT is No Longer Supported |
| Discontinuance | MAX3723UTP+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3723UTP+T | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3784AUTE+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3784AUTE+T | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX3784UTE+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX4399CTK+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX4760AEWX+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX4803ETN+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX5950ETJ+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX5951ETJ+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX5963UTL+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX6946CAWE+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX767SCAP | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX77179EWC+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8629ETI+T | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8645XETI+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8645XETI+T | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8683ETM+TCH1 | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8736BGTL+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 14-Mar-2016

| | | | | | |
|----------------|-----------------|----------------|-------------|-------------|------------------------------------|
| Discontinuance | MAX8736ETL+T | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8739ETP+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8759ETI+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8786GTL+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8798AETX+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX88000EDT+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8844YETD+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8844YETD+T | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8844ZETD+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8844ZETD+T | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX8916ITL+T | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX9515ABS+G45 | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX9515ABS+TG45 | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX9539EUI+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX9552EUD+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX9595CTM+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX9673ETI+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX9673ETI+T | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAX9673ETI+TG0E | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | MAXQ3100-EMN+ | N/A | 13-Aug-2016 | 11-Feb-2018 | Part can no longer be manufactured |
| Discontinuance | SC1869A-00B00E | SC1894A-00C13E | 13-Aug-2016 | 11-Feb-2018 | The part was not released |