



Product Change Notification

TE Connectivity

Product Change Notification: P-16-012566

PCN Date: 28-JAN-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Printing on MT relay

Description of Changes

In course of our ongoing improvement process we realized, that some of the ratings on our MT relays are not well legible resp. understandable. Therefore we are modifying the arrangement of printing just a little, which you can find in the enclosed drawings. There is not any change in the specification itself or any rating. Drawings of the changed printing for relays with special part numbers can be delivered on request.

Other attachments:

[MT Label](#)

Reason for Changes:

Document clarification.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

11-APR-2016

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393092-8	NO			"MT333024", "CE0515-000", "AMPS-1-1393092-8"			
1393092-7	NO			"MT328115", "CE0510-000", "AMPS-0-1393092-7"			
5-1393090-0	NO			"MT221024", "CE0524-000", "AMPS-5-1393090-0"			
7-1393090-0	NO			"MT228115", "CE0539-000", "AMPS-7-1393090-0"			
7-1393091-4	NO			"MT321110", "CE0543-000", "AMPS-7-1393091-4"			
7-1393091-5	NO			"MT321125"			
7-1393091-9	NO			"MT3230C4", "CE0545-000", "AMPS-7-1393091-9"			
8-1393091-4	NO			"MT323024", "CE0553-000", "AMPS-8-1393091-4"			
9-1393091-8	NO			"MT326048", "CE0559-000", "AMPS-9-1393091-8"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393092-8	NO			"MT333024", "CE0515-000", "AMPS-1-1393092-8"			
1393092-7	NO			"MT328115", "CE0510-000", "AMPS-0-1393092-7"			
5-1393090-0	NO			"MT221024", "CE0524-000", "AMPS-5-1393090-0"			
7-1393090-0	NO			"MT228115", "CE0539-000", "AMPS-7-1393090-0"			
7-1393091-4	NO			"MT321110", "CE0543-000", "AMPS-7-1393091-4"			
7-1393091-5	NO			"MT321125"			
7-1393091-9	NO			"MT3230C4", "CE0545-000", "AMPS-7-1393091-9"			
8-1393091-4	NO			"MT323024", "CE0553-000", "AMPS-8-1393091-4"			
9-1393091-8	NO			"MT326048", "CE0559-000", "AMPS-9-1393091-8"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393092-8	NO			"MT333024", "CE0515-000", "AMPS-1-1393092-8"			
1393092-7	NO			"MT328115", "CE0510-000", "AMPS-0-1393092-7"			
5-1393090-0	NO			"MT221024", "CE0524-000", "AMPS-5-1393090-0"			
7-1393090-0	NO			"MT228115", "CE0539-000", "AMPS-7-1393090-0"			
7-1393091-4	NO			"MT321110", "CE0543-000", "AMPS-7-1393091-4"			
7-1393091-5	NO			"MT321125"			
7-1393091-9	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"MT3230C4", "CE0545-000", "AMPS-7-1393091-9"			
8-1393091-4	NO			"MT323024", "CE0553-000", "AMPS-8-1393091-4"			
9-1393091-8	NO			"MT326048", "CE0559-000", "AMPS-9-1393091-8"			