



Product Change Notification - SYST-19EOKS876

Date:	24 Jan 2018
Product Category:	Ultrasound MOSFET Drivers
Affected CPNs:	 
Notification subject:	Data Sheet - MD1715 2-Channel 5-Level High-Speed Ultrasound Driver IC Data Sheet
Notification text:	SYST-19EOKS876

Microchip has released a new DeviceDoc for the MD1715 2-Channel 5-Level High-Speed Ultrasound Driver IC Data Sheet of devices. If you are using one of these devices please read the document located at [MD1715 2-Channel 5-Level High-Speed Ultrasound Driver IC Data Sheet](#).

Notification Status: Final

Description of Change:

- 1) Converted Supertex Doc# DSFP-MD1715 to Microchip DS20005921A
- 2) Changed the package marking format
- 3) Changed the quantity of the 40-lead VQFN K6 M935 package from 2000/Reel to 3000/Reel
- 4) Made minor text changes throughout the document

Pre Change: 40-lead VQFN K6 M935 package from 2000/Reel

Post Change: 40-lead VQFN K6 M935 package to 3000/Reel

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 24 Jan 2018

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s): [MD1715 2-Channel 5-Level High-Speed Ultrasound Driver IC Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

MD1715K6-G-M935

MD1715K6-G