



PRODUCT DISCONTINUANCE
45 day warning
Generic Copy

15-May-2006

SUBJECT: ON Semiconductor Notice of Pending Cancellation #15532

TITLE: 45 days to order notice of devices listed in 4Q 2005 ON Semiconductor PRODUCT DISCONTINUANCE #15180

LAST BUY DATE: 30 Jun 2006

LAST SHIP DATE: 31 Dec 2006

AFFECTED PRODUCT DIVISION:

Discretes Products
Analog Products
Logic Products
ECL Products
Power Products

FOR ANY QUESTIONS CONCERNING THIS NOTIFICATION:

Contact Sales Office or Herve Marchionini <herve.marchionini@onsemi.com>

NOTIFICATION TYPE:

Customers must notify ON Semiconductor in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." ON Semiconductor and the customer may negotiate an appropriate End-of-Life.

DESCRIPTION AND PURPOSE:

This is a reminder that you have 45 days to order devices listed in 4Q 2005 ON Semiconductor PRODUCT DISCONTINUANCE NOTICE #15180 issued on 18-Dec-2005.

In an attempt to minimize the number and frequency of product discontinuance notices to its customers, ON Semiconductor is publishing this quarterly product discontinuance notification.

Some of the devices contained in this notice may be part of a product portfolio renewal process or a manufacturing facility closure. ON Semiconductor continually monitors worldwide sales and billings activities on all the products offered to its customers.

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.



Product Discontinuance #15532

ON Semiconductor wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices. ON Semiconductor has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, ON Semiconductor has partnered with Rochester Electronics who will carry any remaining device inventory as well as mask sets, etc. to potentially allow for a continued source after ON Semiconductor has completed its business process.

PLEASE NOTE: ON Semiconductor may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas & Europe:

Herve Marchionini (email is herve.marchionini@onsemi.com)

33.5.34.61.12.68 or 1.602.244.4170

France

Japan & Asia Pacific:

Nobuyuki Otake (email is nobuyuki.otake@onsemi.com)

81.241.27.5460

Japan

NOTE: SUBSEQUENT TO PUBLISHING A DISCONTINUANCE NOTICE, ON SEMICONDUCTOR WILL ALLOW SIX (6) MONTHS FROM THE ANNOUNCEMENT DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS.

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

End of life buy orders must be placed before June 30, 2006
and End of life buy orders must be shipped before December 31, 2006.



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

Device to be Discontinued	Recommended Replacement	Supplier
1.5KE100ARL4	None	N/A
1.5KE100ARL4G	None	N/A
1.5KE110ARL4	None	N/A
1.5KE110ARL4G	None	N/A
1.5KE120ARL4	None	N/A
1.5KE120ARL4G	None	N/A
1.5KE130A	None	N/A
1.5KE130AG	None	N/A
1.5KE130ARL4	None	N/A
1.5KE130ARL4G	None	N/A
1.5KE150A	None	N/A
1.5KE150AG	None	N/A
1.5KE150ARL4	None	N/A
1.5KE150ARL4G	None	N/A
1.5KE160ARL4	None	N/A
1.5KE160ARL4G	None	N/A
1.5KE170ARL4	None	N/A
1.5KE170ARL4G	None	N/A
1.5KE180A	None	N/A
1.5KE180AG	None	N/A
1.5KE180ARL4	None	N/A
1.5KE180ARL4G	None	N/A
1.5KE200A	None	N/A
1.5KE200AG	None	N/A
1.5KE200ARL4	None	N/A
1.5KE200ARL4G	None	N/A
1.5KE220ARL4	None	N/A
1.5KE220ARL4G	None	N/A
1.5KE250A	None	N/A
1.5KE250AG	None	N/A
1.5KE250ARL4	None	N/A
1.5KE250ARL4G	None	N/A
1.5SMC7.5AT3	1.5SMC7.5AT3G	ON Semi
1N4001FF	None	N/A
1N4001FFG	None	N/A
1N4002FF	None	N/A
1N4002FFG	None	N/A
1N4003FF	None	N/A
1N4003FFG	None	N/A
1N4004FF	None	N/A
1N4004FFG	None	N/A
1N4005FF	None	N/A
1N4005FFG	None	N/A
1N5951BRL	1N5951BRLG	ON Semi
1N6269A	None	N/A
1N6269AG	None	N/A



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

Device to be Discontinued	Recommended Replacement	Supplier
1N6299A	None	N/A
1N6299AG	None	N/A
1N6299ARL4	None	N/A
1N6299ARL4G	None	N/A
1N6300A	None	N/A
1N6300AG	None	N/A
1N6301A	None	N/A
1N6301AG	None	N/A
1N6302A	None	N/A
1N6302AG	None	N/A
1N6303A	None	N/A
1N6303AG	None	N/A
1N6303ARL4	None	N/A
1N6303ARL4G	None	N/A
1PMT18AT1	None	N/A
1PMT28AT1	1PMT28AT1G	ON Semi
1PMT40AT1	None	N/A
1PMT5939BT1	1PMT5939BT1G	ON Semi
1SMA14CAT3	1SMA14CAT3G	ON Semi
1SMA17AT3	1SMA17AT3G	ON Semi
1SMA28CAT3	1SMA28CAT3G	ON Semi
1SMA40AT3	1SMA40AT3G	ON Semi
1SMA48AT3	1SMA48AT3G	ON Semi
1SMA48CAT3	1SMA48CAT3G	ON Semi
1SMA54CAT3	1SMA54CAT3G	ON Semi
1SMA58CAT3	1SMA58CAT3G	ON Semi
1SMA7.5AT3	1SMA7.5AT3G	ON Semi
1SMA8.0AT3	1SMA8.0AT3G	ON Semi
1SMC8.5AT3	1SMC8.5AT3G	ON Semi
BC337-016	BC337-016G	ON Semi
BC487	BC487G	ON Semi
BC847CPDW1T1	None	N/A
BC858CLT3	BC858CLT3G	ON Semi
BC859BLT3	BC859BLT3G	ON Semi
BCW33LT3	BCW33LT3G	ON Semi
BCX18LT1	BCX18LT1G	ON Semi
BF422RL1	BF422RL1G	ON Semi
BF720T3	BF720T3G	ON Semi
BSR58LT1	BSR58LT1G	ON Semi
BUC6323ZCDIE	None	N/A
BZX84B18LT3	None	N/A
BZX84B7V5LT1	BZX84B7V5LT1G	ON Semi
BZX84C11LT3	BZX84C11LT3G	ON Semi
BZX84C12ET1	BZX84C12ET1G	ON Semi
BZX84C16ET3	BZX84C16ET3G	ON Semi
BZX84C3V3LT3	BZX84C3V3LT3G	ON Semi



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

Device to be Discontinued	Recommended Replacement	Supplier
BZX84C5V1ET1	BZX84C5V1ET1G	ON Semi
BZX84C5V1ET3	BZX84C5V1ET3G	ON Semi
BZX84C62LT3	BZX84C62LT3G	ON Semi
BZX84C68LT3	BZX84C68LT3G	ON Semi
J111RLRA	J111RLRAG	ON Semi
LC945P	None	N/A
LC945PRLRA	None	N/A
LM323AT	None	N/A
LM323T	None	N/A
LM323TG	None	N/A
LMB30VL2WP	None	N/A
LMB33VL2WP	None	N/A
LMB36VL2WP	None	N/A
LMB39VL2WP	None	N/A
LMB3V0L2WP	None	N/A
LMB3V3C2WP	None	N/A
LMB3V3L2WP	None	N/A
LMB3V6C2WP	None	N/A
LMB3V6L2WP	None	N/A
LMB3V9C2WP	None	N/A
LMB3V9L1WP	None	N/A
LMB3V9L2WP	None	N/A
LMB47VL2WP	None	N/A
LMB4V3C2WP	None	N/A
LMB4V3L2WP	None	N/A
LMB4V7C2WP	None	N/A
LMB4V7L2WP	None	N/A
LMB6V2C2WP	None	N/A
LMB6V2L2WP	None	N/A
LMB6V8C2WP	None	N/A
LMB6V8L1WP	None	N/A
LN1B15VF1WP	None	N/A
LOC16VWP	None	N/A
LOC9V1WP	None	N/A
LOD22VC2WP	None	N/A
LOD24VC2WP	None	N/A
LOD27VC2WP	None	N/A
LOD2V4C2WP	None	N/A
LOD2V7C2WP	None	N/A
LOD30VC2WP	None	N/A
LOD33VC2WP	None	N/A
LOD3V0C2WP	None	N/A
LOD3V3C2WP	None	N/A
LOD3V6C2WP	None	N/A
LOD3V9C2WP	None	N/A
LSR6000CP	None	N/A



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

Device to be Discontinued	Recommended Replacement	Supplier
LV2209	LV2209G	ON Semi
MAC4N	None	N/A
MAC9M	MAC9MG	ON Semi
MBD110DWT1	MBD110DWT1G	ON Semi
MBR1545CTP	None	N/A
MBR20100CTP	None	N/A
MBR2045CTP	None	N/A
MBR2545CTP	None	N/A
MBRP20030CTL	None	N/A
MBRP20030CTLG	None	N/A
MBRP20045CT	None	N/A
MBRP20045CTG	None	N/A
MBRP20060CT	None	N/A
MBRP20060CTG	None	N/A
MBRP30045CT	None	N/A
MBRP30045CTG	None	N/A
MBRP30060CT	None	N/A
MBRP30060CTG	None	N/A
MBRP400100CTL	None	N/A
MBRP400100CTLG	None	N/A
MBRP40030CTL	None	N/A
MBRP40030CTLG	None	N/A
MBRP40045CTL	None	N/A
MBRP40045CTLG	None	N/A
MBRP60035CTL	None	N/A
MBRP60035CTLG	None	N/A
MC14001BFEL	soic REPLACEMENT	
MC14007UBFEL	soic REPLACEMENT	
MC14016BFEL	soic REPLACEMENT	
MC14017BFEL	soic REPLACEMENT	
MC14020BFEL	soic REPLACEMENT	
MC14020BFELG	soic REPLACEMENT	
MC14021BFEL	soic REPLACEMENT	
MC14024BFEL	soic REPLACEMENT	
MC14025BFEL	soic REPLACEMENT	
MC14027BFEL	soic REPLACEMENT	
MC14027BFELG	soic REPLACEMENT	
MC14028BFEL	soic REPLACEMENT	
MC14029BFEL	soic REPLACEMENT	
MC14040BFEL	soic REPLACEMENT	
MC14043BFEL	soic REPLACEMENT	
MC14049BFEL	soic REPLACEMENT	
MC14060BFEL	soic REPLACEMENT	
MC14070BFEL	soic REPLACEMENT	
MC14071BFEL	soic REPLACEMENT	
MC14073BFEL	soic REPLACEMENT	



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

<u>Device to be Discontinued</u>	<u>Recommended Replacement</u>	<u>Supplier</u>
MC14077BFEL	soic REPLACEMENT	
MC14099BFEL	soic REPLACEMENT	
MC14175BFEL	soic REPLACEMENT	
MC14503BFEL	soic REPLACEMENT	
MC14516BFEL	soic REPLACEMENT	
MC14516BFELG	soic REPLACEMENT	
MC14518BFEL	soic REPLACEMENT	
MC14518BFELG	soic REPLACEMENT	
MC14520BFEL	soic REPLACEMENT	
MC14520BFELG	soic REPLACEMENT	
MC14521BFEL	soic REPLACEMENT	
MC14526BF	soic REPLACEMENT	
MC14543BF	soic REPLACEMENT	
MC14557BF	soic REPLACEMENT	
MC14585BFEL	soic REPLACEMENT	
MC34063AM	MC34063AMG	ON Semi
MC34063AMEL	MC34063AMELG	ON Semi
MC34063BD	MC33063AD	ON Semi
MC34063BDG	MC33063ADG	ON Semi
MC34063BDR2	MC33063ADR2	ON Semi
MC34063BDR2G	MC33063ADR2G	ON Semi
MC44603DW	MC44603ADW	ON Semi
MC44603DWG	MC44603ADWG	ON Semi
MC44603DWR2	MC44603ADWR2	ON Semi
MC44603DWR2G	MC44603ADWR2G	ON Semi
MC44603P	MC44603AP	ON Semi
MC44603PG	MC44603APG	ON Semi
MC74AC00MEL	soic REPLACEMENT	
MC74AC02MEL	soic REPLACEMENT	
MC74AC04MEL	soic REPLACEMENT	
MC74AC11MEL	soic REPLACEMENT	
MC74AC125MEL	soic REPLACEMENT	
MC74AC138M	soic REPLACEMENT	
MC74AC138MEL	soic REPLACEMENT	
MC74AC157MEL	soic REPLACEMENT	
MC74AC20MEL	soic REPLACEMENT	
MC74AC244MEL	soic REPLACEMENT	
MC74AC245M	soic REPLACEMENT	
MC74AC245MEL	soic REPLACEMENT	
MC74AC259MEL	soic REPLACEMENT	
MC74AC273MEL	soic REPLACEMENT	
MC74AC32MEL	soic REPLACEMENT	
MC74AC373MEL	soic REPLACEMENT	
MC74AC374MEL	soic REPLACEMENT	
MC74AC4040MEL	soic REPLACEMENT	



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

<u>Device to be Discontinued</u>	<u>Recommended Replacement</u>	<u>Supplier</u>
MC74AC573MEL	soic REPLACEMENT	
MC74AC574M	soic REPLACEMENT	
MC74AC74MEL	soic REPLACEMENT	
MC74ACT00MEL	soic REPLACEMENT	
MC74ACT02MEL	soic REPLACEMENT	
MC74ACT04M	soic REPLACEMENT	
MC74ACT04MEL	soic REPLACEMENT	
MC74ACT04MELG	soic REPLACEMENT	
MC74ACT05MEL	soic REPLACEMENT	
MC74ACT08MEL	soic REPLACEMENT	
MC74ACT08MELG	soic REPLACEMENT	
MC74ACT11MEL	soic REPLACEMENT	
MC74ACT14MEL	soic REPLACEMENT	
MC74ACT157MEL	soic REPLACEMENT	
MC74ACT161MEL	soic REPLACEMENT	
MC74ACT240MEL	soic REPLACEMENT	
MC74ACT244MEL	soic REPLACEMENT	
MC74ACT245M	soic REPLACEMENT	
MC74ACT245MEL	soic REPLACEMENT	
MC74ACT273MEL	soic REPLACEMENT	
MC74ACT273MELG	soic REPLACEMENT	
MC74ACT299DW	None	N/A
MC74ACT299DWG	None	N/A
MC74ACT299DWR2	None	N/A
MC74ACT299DWR2G	None	N/A
MC74ACT299N	None	N/A
MC74ACT299NG	None	N/A
MC74ACT32MEL	soic REPLACEMENT	
MC74ACT32MELG	soic REPLACEMENT	
MC74ACT373MEL	soic REPLACEMENT	
MC74ACT374MEL	soic REPLACEMENT	
MC74ACT574MEL	soic REPLACEMENT	
MC74ACT74MEL	soic REPLACEMENT	
MC74ACT86MEL	soic REPLACEMENT	
MC74HC02AFEL	soic REPLACEMENT	
MC74HC02AFELG	soic REPLACEMENT	
MC74HC03AFEL	soic REPLACEMENT	
MC74HC126AFEL	soic REPLACEMENT	
MC74HC132AFEL	soic REPLACEMENT	
MC74HC138AF	soic REPLACEMENT	
MC74HC138AFEL	soic REPLACEMENT	
MC74HC138AFELG	soic REPLACEMENT	
MC74HC139AFEL	soic REPLACEMENT	
MC74HC157AFEL	soic REPLACEMENT	



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

<u>Device to be Discontinued</u>	<u>Recommended Replacement</u>	<u>Supplier</u>
MC74HC164AFEL	soic REPLACEMENT	
MC74HC164AFELG	soic REPLACEMENT	
MC74HC174AFEL	soic REPLACEMENT	
MC74HC175AFEL	soic REPLACEMENT	
MC74HC240AFEL	soic REPLACEMENT	
MC74HC245AF	soic REPLACEMENT	
MC74HC245AFEL	soic REPLACEMENT	
MC74HC373AF	soic REPLACEMENT	
MC74HC373AFEL	soic REPLACEMENT	
MC74HC374AF	soic REPLACEMENT	
MC74HC374AFEL	soic REPLACEMENT	
MC74HC374AFELG	soic REPLACEMENT	
MC74HC390AF	soic REPLACEMENT	
MC74HC390AFEL	soic REPLACEMENT	
MC74HC4020AF	soic REPLACEMENT	
MC74HC4020AFEL	soic REPLACEMENT	
MC74HC4040AFEL	soic REPLACEMENT	
MC74HC4052AF	soic REPLACEMENT	
MC74HC4052AFEL	soic REPLACEMENT	
MC74HC4052AFELG	soic REPLACEMENT	
MC74HC4060AFEL	soic REPLACEMENT	
MC74HC4316AFEL	soic REPLACEMENT	
MC74HC540AF	soic REPLACEMENT	
MC74HC540AFEL	soic REPLACEMENT	
MC74HC573AFEL	soic REPLACEMENT	
MC74HC589AFEL	soic REPLACEMENT	
MC74HCT04AFEL	soic REPLACEMENT	
MC74HCT14AFEL	soic REPLACEMENT	
MC74HCT244AF	soic REPLACEMENT	
MC74HCT244AFEL	soic REPLACEMENT	
MC74HCT245AFEL	soic REPLACEMENT	
MC74HCT374AFEL	soic REPLACEMENT	
MC74HCT541AF	soic REPLACEMENT	
MC74LCX00MEL	soic REPLACEMENT	
MC74LCX04MEL	soic REPLACEMENT	
MC74LCX07M	soic REPLACEMENT	
MC74LCX08MEL	soic REPLACEMENT	
MC74LCX139M	soic REPLACEMENT	
MC74LCX14M	soic REPLACEMENT	
MC74LCX14MEL	soic REPLACEMENT	
MC74LCX244MEL	soic REPLACEMENT	
MC74LCX245M	soic REPLACEMENT	
MC74LCX245MEL	soic REPLACEMENT	
MC74LCX540MEL	soic REPLACEMENT	
MC74LCX541MEL	soic REPLACEMENT	
MC74VHC00MEL	soic REPLACEMENT	



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

<u>Device to be Discontinued</u>	<u>Recommended Replacement</u>	<u>Supplier</u>
MC74VHC04MEL	soic REPLACEMENT	
MC74VHC08MEL	soic REPLACEMENT	
MC74VHC125M	soic REPLACEMENT	
MC74VHC125MEL	soic REPLACEMENT	
MC74VHC132MEL	soic REPLACEMENT	
MC74VHC244MEL	soic REPLACEMENT	
MC74VHC32MEL	soic REPLACEMENT	
MC74VHC373MEL	soic REPLACEMENT	
MC74VHC374MEL	soic REPLACEMENT	
MC74VHC74MEL	soic REPLACEMENT	
MC74VHC86MEL	soic REPLACEMENT	
MC74VHCT04AMEL	soic REPLACEMENT	
MC74VHCT240AMEL	soic REPLACEMENT	
MC74VHCT245AMEL	soic REPLACEMENT	
MC74VHCU04MEL	soic REPLACEMENT	
MC78T05ABT	None	N/A
MC78T05ACT	None	N/A
MC78T05ACTG	None	N/A
MC78T05BT	None	N/A
MC78T05BTG	None	N/A
MC78T05CD2T	None	N/A
MC78T05CD2TR4	None	N/A
MC78T05CT	None	N/A
MC78T05CTG	None	N/A
MC78T08CT	None	N/A
MC78T08CTG	None	N/A
MC78T12ACT	None	N/A
MC78T12ACTG	None	N/A
MC78T12BT	None	N/A
MC78T12BTG	None	N/A
MC78T12CT	None	N/A
MC78T12CTG	None	N/A
MC78T15ABT	None	N/A
MC78T15ACT	None	N/A
MC78T15CT	None	N/A
MC78T15CTG	None	N/A
MJC15012WP	None	N/A
MJC2955WP	None	N/A
MKP3V120	MKP3V120G	ON Semi
MM3Z30VT1	MM3Z30VT1G	ON Semi
MM3Z6V2ST1	MM3Z6V2ST1G	ON Semi
MMBC1321Q4LT1	MMBC1321Q4LT1G	ON Semi
MMBD701LT3	MMBD701LT3G	ON Semi
MMBT2132T3	MMBT2132T3G	ON Semi
MMBT2369ALT3	MMBT2369ALT3G	ON Semi
MMBT4401WT1	MMBT4401WT1G	ON Semi



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

Device to be Discontinued	Recommended Replacement	Supplier
MMBV809LT3	MMBV809LT3G	ON Semi
MMBZ15VALT3	MMBZ15VALT3G	ON Semi
MMBZ20VALT3	MMBZ20VALT3G	ON Semi
MMBZ5226BLT3	MMBZ5226BLT3G	ON Semi
MMBZ5228ELT1	MMBZ5228ELT1G	ON Semi
MMBZ5230BLT3	MMBZ5230BLT3G	ON Semi
MMBZ5230ELT1	MMBZ5230ELT1G	ON Semi
MMBZ5234ELT1	MMBZ5234ELT1G	ON Semi
MMBZ5235BLT3	MMBZ5235BLT3G	ON Semi
MMBZ5237BLT3	MMBZ5237BLT3G	ON Semi
MMBZ5250BLT3	MMBZ5250BLT3G	ON Semi
MMBZ5257ELT1	MMBZ5257ELT1G	ON Semi
MMBZ5259BLT3	MMBZ5259BLT3G	ON Semi
MMSZ10ET1	MMSZ10ET1G	ON Semi
MMSZ18ET1	MMSZ18ET1G	ON Semi
MMSZ20ET1	MMSZ20ET1G	ON Semi
MMSZ22ET1	MMSZ22ET1G	ON Semi
MMSZ30ET1	MMSZ30ET1G	ON Semi
MMSZ4678T3	MMSZ4678T3G	ON Semi
MMSZ4688T3	MMSZ4688T3G	ON Semi
MMSZ47T1	MMSZ47T1G	ON Semi
MMSZ5222ET1	MMSZ5222ET1G	ON Semi
MMSZ5229BT3	MMSZ5229BT3G	ON Semi
MMSZ5236BT3	MMSZ5236BT3G	ON Semi
MMSZ5241ET1	MMSZ5241ET1G	ON Semi
MMSZ5242BT3	MMSZ5242BT3G	ON Semi
MMSZ5252BT3	MMSZ5252BT3G	ON Semi
MMSZ5252ET3	MMSZ5252ET3G	ON Semi
MMSZ5257BT3	MMSZ5257BT3G	ON Semi
MMSZ5267BT3	MMSZ5267BT3G	ON Semi
MMSZ5V1T3	MMSZ5V1T3G	ON Semi
MMSZ5V6ET1	MMSZ5V6ET1G	ON Semi
MMSZ7V5ET1	MMSZ7V5ET1G	ON Semi
MMUN2131LT1	MMUN2131LT1G	ON Semi
MPS2907ARLRE	MPS2907ARLREG	ON Semi
MPS8599RLRM	MPS8599RLRMG	ON Semi
MPSA42RLRF	MPSA42RLRFG	ON Semi
MPSH17RLRA	MPSH17RLRAG	ON Semi
MR856FF	None	N/A
MR856FFG	None	N/A
MSB92AWT1	MSB92AWT1G	ON Semi
MSD601-ST1	MSD601-ST1G	ON Semi
MTD20N06VT4	None	N/A
MTP29N15E	None	N/A
MUN2115T1	MUN2115T1G	ON Semi
MUN5115DW1T1	MUN5115DW1T1G	ON Semi



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

Device to be Discontinued	Recommended Replacement	Supplier
MUR1100EFF	None	N/A
MUR1100EFFG	None	N/A
MUR120FF	None	N/A
MUR120FFG	None	N/A
MUR160FF	None	N/A
MUR160FFG	None	N/A
MUR460FF	None	N/A
MUR460FFG	None	N/A
MURP20020CT	None	N/A
MURP20020CTG	None	N/A
MURP20040CT	None	N/A
MURP20040CTG	None	N/A
NCP1508EVB	None	N/A
NCP1508MNR2	None	N/A
NCP1508MNR2G	NCP1521ASNT1G	ON Semi
NCP1509EVB	None	N/A
NCP1509MNR2G	NCP1521ASNT1G	ON Semi
NCP1835MN24R2	NCP1835MN24T2	ON Semi
NCP1835MN24R2G	NCP1835MN24T2G	ON Semi
NCP2809AEVB	None	N/A
NCP2809BEVB	None	N/A
NCS5000SNT1	None	N/A
NCS5000SNT1G	None	N/A
NJV2N6388	None	N/A
NJV2N6388G	None	N/A
NJVBDW42	None	N/A
NJVBDW42G	None	N/A
NJVBDX33B	None	N/A
NJVBDX33BG	None	N/A
NJVBDX33C	None	N/A
NJVBDX33CG	None	N/A
NJVMJD253T4	None	N/A
NJVMJD253T4G	None	N/A
NJVMJD350T4	None	N/A
NJVMJD350T4G	None	N/A
NJVMJD44H11RL	None	N/A
NJVMJD44H11RLG	None	N/A
NJVMJD45H11T4	None	N/A
NJVMJD45H11T4G	None	N/A
NJVMJE15031	None	N/A
NJVMJE15031G	None	N/A
NJVTIP42B	None	N/A



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

Device to be Discontinued	Recommended Replacement	Supplier
NJVTIP42BG	None	N/A
NJVTIP42C	None	N/A
NJVTIP42CG	None	N/A
NRVA4004T3	None	N/A
NRVA4004T3G	None	N/A
NRVB0540T1	None	N/A
NRVB0540T1G	None	N/A
NRVB10100	None	N/A
NRVB10100G	None	N/A
NRVB2545CT	None	N/A
NRVB2545CTG	None	N/A
NRVB745	None	N/A
NRVB745G	None	N/A
NRVBS240LT3	None	N/A
NRVBS240LT3G	None	N/A
NRVU1560	None	N/A
NRVU1560G	None	N/A
NSBC143TDXV6T5	NSBC143TDXV6T5G	ON Semi
NSBC144EPDXV6T5	NSBC144EPDXV6T5G	ON Semi
NSVMMD352WT1	NSVMMD352WT1G	ON Semi
NTC24N06LTR	None	N/A
NTC24N06WP	None	N/A
NTD78N03R	None	N/A
NTD78N03R-001	None	N/A
NTD78N03R-035	None	N/A
NTD78N03R-1G	None	N/A
NTD78N03R-35G	None	N/A
NTD78N03RG	None	N/A
NTD78N03RT4	None	N/A
NTD78N03RT4G	None	N/A
NTL4502NT1	None	N/A
NTMS4700NR2	None	N/A
NTMS4700NR2G	None	N/A
NTMS4704NR2	None	N/A
NTMS4704NR2G	None	N/A
P6KE100ARL	P6KE100ARLG	ON Semi
P6KE200B	P6KE200BG	ON Semi
P6KE62A	P6KE62AG	ON Semi
P6SMB22CAT3	P6SMB22CAT3G	ON Semi
P6SMB75CAT3	P6SMB75CAT3G	ON Semi
SA40ARL	SA40ARLG	ON Semi
SA60ARL	SA60ARLG	ON Semi
SA8.0A	None	N/A
SBAS40-06LT1	SBAS40-06LT1G	ON Semi
SBAV70WT1	SBAV70WT1G	ON Semi
SBR182CT	None	N/A



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

Device to be Discontinued	Recommended Replacement	Supplier
SBR205UK	None	N/A
SBR5495-1S	None	N/A
SBR5571-002	None	N/A
SBR81045	None	N/A
SBR81045G	None	N/A
SBRB106CTT4	None	N/A
SBRB20100CT	None	N/A
SBRB20100CTG	None	N/A
SBRB2515LT4	None	N/A
SBRB2515LT4G	None	N/A
SBRB3030CTT4	None	N/A
SBRB3030CTT4G	None	N/A
SBRC164WP	None	N/A
SBRC2545CTRL	None	N/A
SBRC5631RL	None	N/A
SBRD112-3CTT4	None	N/A
SBRM120LT3	None	N/A
SBRS5636-6T3	None	N/A
SBRS5649T3	None	N/A
SBRS8120T3	None	N/A
SBRS8120T3G	None	N/A
SBRS8130T3	None	N/A
SBRS8130T3G	None	N/A
SBRS8330T3	None	N/A
SBRS8330T3G	None	N/A
SC111018DR2	UC2842BD	ON Semi
SC2842AN	UC2842BN	ON Semi
SC79157DR2	UC2842BD	ON Semi
SC79178DR2	SC79178ADR2	ON Semi
SCR2149A	None	N/A
SCR2160LFDP	None	N/A
SCR22-6RLRP	SCR22-6RLRPG	ON Semi
SE0G6P2B1T	None	N/A
SE0M9P1B5P	None	N/A
SJ7159	None	N/A
SJ7160	None	N/A
SJ7196	None	N/A
SJB42CG	None	N/A
SJD1044T4	None	N/A
SJD1044T4G	None	N/A
SJD117T4G	None	N/A
SJD32C1	None	N/A
SJD32C1G	None	N/A
SJD32CG	None	N/A
SJD32CRL	None	N/A



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

Device to be Discontinued	Recommended Replacement	Supplier
SJD32CRLG	None	N/A
SJD44H11-1G	None	N/A
SJD44H11G	None	N/A
SJD44H11RLG	None	N/A
SJD44H11T4	None	N/A
SJD44H11T4G	None	N/A
SJD45H11	None	N/A
SJD45H11-001	None	N/A
SJD45H11-1G	None	N/A
SJD45H11G	None	N/A
SJD45H11RL	None	N/A
SJD45H11RLG	None	N/A
SJE2930LFBL	None	N/A
SJE6420	None	N/A
SJE8031	None	N/A
SMBD1023T	None	N/A
SMBD1087LT1	None	N/A
SMBD1106LT1	None	N/A
SMBD1108LT3	None	N/A
SMF170AT1	SMF170AT1G	ON Semi
SMF18AT1	SMF18AT1G	ON Semi
SMF54AT1	SMF54AT1G	ON Semi
SMF64AT1	SMF64AT1G	ON Semi
SMF70AT1	SMF70AT1G	ON Semi
SMFT3055VT3	None	N/A
SMMBT3904LT3	SMMBT3904LT3G	ON Semi
SMMBT3906LT3	SMMBT3906LT3G	ON Semi
SMMUN2233LT1	SMMUN2233LT1G	ON Semi
SMQA1001T1	None	N/A
SMQA5600T1	None	N/A
SMQA5600T3	None	N/A
SMQA5600T3G	None	N/A
SMUN2112T1	SMUN2112T1G	ON Semi
SMUN2216T1	None	N/A
SR2302KRL	None	N/A
SR2607	None	N/A
SR3773	None	N/A
SR3980	None	N/A
SR4003ARL	None	N/A
SR4003ARLG	None	N/A
SR4007ARL	None	N/A
SR4007ARLG	None	N/A
SR4116LRL	None	N/A
SR4358LF	None	N/A
SR4373	None	N/A
SR4413LC	None	N/A



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

Device to be Discontinued	Recommended Replacement	Supplier
SR4415-1LF	None	N/A
SR4418LC	None	N/A
SR4421LRL	None	N/A
SR4423LF	None	N/A
SR4434LF	None	N/A
SR4446	None	N/A
SR4450LF	None	N/A
SR4487	None	N/A
SR4822	None	N/A
SR4936ARL	None	N/A
SR4936ARLG	None	N/A
SR4937ARL	None	N/A
SR751B	None	N/A
SR852ARL	None	N/A
SR852ARLG	None	N/A
SR854ARL	None	N/A
SR854ARLG	None	N/A
SRA5300T3	None	N/A
SRA5300T3G	None	N/A
SRB5084T3	None	N/A
SRB5084T3G	None	N/A
SRJ4413LRL	None	N/A
SRJ4415-1LF	None	N/A
SRJ4418LF	None	N/A
SRJ4483LF	None	N/A
SSTUMT1DMW6T1	None	N/A
STB1548T4	None	N/A
STB30P06VT4	None	N/A
STB75N05HDT4	None	N/A
STD110N02R-011	STD	ON Semi
STD70N03RT4	None	N/A
STW1019	None	N/A
SUR114C	None	N/A
SUR280S	None	N/A
SUR328	None	N/A
SUR333CTR	None	N/A
SUR81620CTR	None	N/A
SUR8820	None	N/A
SUR8820G	None	N/A
SURB1620CT	None	N/A
SURC160TR	None	N/A
SURD108LFKBT4	None	N/A
SURD112T4	None	N/A
SURD113CTT4	None	N/A
SURD114CTT4	None	N/A



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

<u>Device to be Discontinued</u>	<u>Recommended Replacement</u>	<u>Supplier</u>
SURHB860CTT4	None	N/A
SURHB860CTT4G	None	N/A
SURS5630-4T3	None	N/A
SURS5661T3	None	N/A
SURS8110T3	None	N/A
SURS8110T3G	None	N/A
SZ1.5KE250ARL4	None	N/A
SZMQA27VT1	None	N/A
TE02196T	None	N/A
TE02208	None	N/A
TMBT0104LT1	TMBT0104LT1G	ON Semi
TP00247ZL1	TP00247ZL1G	ON Semi
TR00195-003	None	N/A
TR00256-001	None	N/A
TR00288	None	N/A
TR00296-004	None	N/A
TR00304	None	N/A
TR00305G	None	N/A
UC2842AD	UC2842BD	ON Semi
UC2842ADG	UC2842BDG	ON Semi
UC2842ADR2	UC2842BD	ON Semi
UC2842ADR2G	UC2842BDG	ON Semi
UC2842AN	UC2842BN	ON Semi
UC2842ANG	UC2842BNG	ON Semi
UC2843AD	UC2843BD	ON Semi
UC2843AD1	UC2843BD1	ON Semi
UC2843AD1G	UC2843BD1G	ON Semi
UC2843AD1R2	UC2843BD1R2	ON Semi
UC2843AD1R2G	UC2843BD1R2G	ON Semi
UC2843ADG	UC2843BDR2G	ON Semi
UC2843ADR2	UC2843BDR2	ON Semi
UC2843ADR2G	UC2843BDR2G	ON Semi
UC2843AN	UC2843BN	ON Semi
UC2843ANG	UC2843BNG	ON Semi
UC2844D	UC2844BDR2	ON Semi
UC2844DG	UC2844BDR2G	ON Semi
UC2844DR2	UC2844BDR2	ON Semi
UC2844DR2G	UC2844BDR2G	ON Semi
UC2844N	UC2844BN	ON Semi
UC2844NG	UC2844BNG	ON Semi
UC2845D	UC2845BD	ON Semi
UC2845DG	UC2845BDG	ON Semi
UC2845DR2	UC2845BDR2	ON Semi
UC2845DR2G	UC2845BDR2G	ON Semi
UC2845N	UC3845BN	ON Semi
UC2845NG	UC3845BNG	ON Semi



Product Discontinuance #15532

POSSIBLE REPLACEMENT PARTS:

Device to be Discontinued	Recommended Replacement	Supplier
UC3842AD	UC3842BD	ON Semi
UC3842ADG	UC3842BDG	ON Semi
UC3842ADR2	UC3842BDR2	ON Semi
UC3842ADR2G	UC3842BDR2G	ON Semi
UC3842AN	UC3842BN	ON Semi
UC3842AN2	UC3842BN	ON Semi
UC3842AN2G	UC3842BNG	ON Semi
UC3842ANG	UC3842BNG	ON Semi
UC3843AD	UC3843BD	ON Semi
UC3843AD1	UC3843BD1	ON Semi
UC3843AD1G	UC3843BD1G	ON Semi
UC3843AD1R2	UC3843BD1R2	ON Semi
UC3843AD1R2G	UC3843BD1R2G	ON Semi
UC3843AD2R2	UC3843BDR2	ON Semi
UC3843AD2R2G	UC3843BDR2G	ON Semi
UC3843ADG	UC3843BDG	ON Semi
UC3843ADR2	UC3843BDR2	ON Semi
UC3843ADR2G	UC3843BDR2G	ON Semi
UC3843AN	UC3843BN	ON Semi
UC3843AN2	UC3843BN	ON Semi
UC3843AN2G	UC3843BNG	ON Semi
UC3843ANG	UC3843BNG	ON Semi
UC3844D	UC3844BD	ON Semi
UC3844DG	UC3844BDG	ON Semi
UC3844DR2	UC3844BDR2	ON Semi
UC3844DR2G	UC3844BDR2G	ON Semi
UC3844N	UC3844BN	ON Semi
UC3844NG	UC3844BNG	ON Semi
UC3845D	UC3845BD	ON Semi
UC3845DG	UC3845BDG	ON Semi
UC3845DR2	UC3845BDR2	ON Semi
UC3845DR2G	UC3845BDR2G	ON Semi
UC3845N	UC3845BN	ON Semi
UC3845NG	UC3845BNG	ON Semi
UMC2NT1	UMC2NT1G	ON Semi