

TE Connectivity

Product Change Notification: P-22-022920

PCN Date: 15-JUN-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

| General Product Description: | |
|------------------------------|--|
| AMP Multifitting MkII | |

Description of Changes

The following Part Numbers will be transferred from Collegno Italy (TE Connectivity manufacturing location) to Outside vendor in Czech.

Reason for Changes:

Dear Customer, as a result of manufacturing footprint optimization, we hereby inform you about a transfer of tools and processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. No change on material, drawing and design. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance. All the certifications will also be updated with the new manufacturing location.

| estimated Dates: | | | | | |
|--|--|--|--|--|--|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): | | | | |
| | 15-AUG-2022 | | | | |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): | | | | |
| | 15-JUN-2023 | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 1-1534072-3 | NO | 8 | | | | | 2 |
| 1-1534072-7 | NO | | | | | | |
| <u>1-1534072-8</u> | NO | | | | | | |
| <u>1-1534073-3</u> | NO | | | | | | |
| 1-1534077-3 | NO | | | | | | |
| <u>1534072-1</u> | NO | | | | | | |
| <u>1534072-2</u> | NO | | | | | | |
| <u>1534072-3</u> | NO | | | | | | |
| <u>1534072-5</u> | NO | | | | | | |
| <u>1534073-1</u> | NO | | | | | | |
| <u>1534073-3</u> | NO | | | | | | |
| <u>1534073-4</u> | NO | | | | | | |
| <u>1534077-2</u> | NO | | | | | | |
| <u>1534077-3</u> | NO | | | | | | |
| <u>1534077-4</u> | NO | | | | | | |
| 2-1534073-4 | NO | | | | | | |
| <u>2178661-3</u> | NO | | | | | | |