



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000854

DATE: 23-May-2017

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX31785K#	N/A			Part reactivated from prior notice: M000847
Lead-Free Conversion	DS2433AX-S#T	DS24B33Q+T&R	23-May-2017	23-May-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS2433X-300-EC	DS2433X-300-EC+	23-May-2017	23-May-2017	Part is leaded. Request information on lead-free version
Discontinuance	73S1210F-68MR/F/PH	N/A	23-May-2017	23-May-2017	Part can no longer be manufactured
Discontinuance	MAX2087ACXD+	MAX2087CXD+	23-May-2018	22-Nov-2018	The part was not released
Discontinuance	MAX31953EVKIT#	N/A	23-May-2017	23-May-2017	EVKIT is No Longer Supported
Discontinuance	MAX31963EVKIT#	N/A	23-May-2017	23-May-2017	EVKIT is No Longer Supported
Discontinuance	MAX3785EVKIT	MAX3785UTTEVKIT	23-May-2017	23-May-2017	EVKIT is No Longer Supported
Discontinuance	MAX4090AAUT+	N/A	23-May-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX4090AAUT+T	N/A	23-May-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX4090AAXT+	N/A	23-May-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX4090AAXT+T	N/A	23-May-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX4090EUT+	N/A	23-May-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX4090EVKIT+	N/A	23-May-2017	23-May-2017	EVKIT is No Longer Supported
Discontinuance	MAX4090EXT+	N/A	23-May-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX4090EXT+T	N/A	23-May-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX9688ETI+	N/A	23-May-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	MAXQ614V-2554+TW	N/A	23-May-2017	23-May-2017	Part can no longer be manufactured
Discontinuance	ZA9L0022NW1LSGA021	MAX32590-L5S+	22-Nov-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L003FNW1LSGA309	MAX32590-L5S+	22-Nov-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L004BNW1LSGA307	MAX32590-L5S+	22-Nov-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L0065NW1LSGA311	MAX32590-L5S+	22-Nov-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L0071NW1LSGA314	MAX32590-L5S+	22-Nov-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L0075NW1LSGA303	MAX32590-L5S+	22-Nov-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L00D0NW1LSGA399	MAX32590-L5S+	22-Nov-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L015DNW1LSGA308	MAX32590-L5S+	22-Nov-2018	22-Nov-2018	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 23-Jun-2017

Discontinuance	ZA9L102BNW2CSGA432	MAX32590-L5S+	22-Nov-2018	22-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L1043NW2CSGA427	MAX32590-L5S+	22-Nov-2018	22-Nov-2018	Part can no longer be manufactured