

PDN Number:	20160729001 B	PDN Date:	Oct. 6, 2016
Title:	Discontinuance of Select Devices sourced in Dongbu foundry		
Customer Contact:	PCN Manager	Dept:	Quality Services
Last date to order:	Feb 3, 2017	Last date to ship:	Feb 3, 2018
Change Type:	Product Discontinuance - End Of Life		

Product Discontinuance Notification Details

Description of Discontinuance:

This purpose of this Revision B is to make corrections to the following:

- 1) Retract 19 devices originally identified for discontinuance (denoted with ~~strikethrough~~ in Product Affected Section, Group 1). These devices will continue to be supported.**
- 2) Add 2 devices to the Product Affected Section. These devices were inadvertently not included in the original notification and will be discontinued (Refer to Product Affected Section Group 2 for affected devices).**
- 3) Correct some of the recommended replacement parts for a subset of devices which are still being discontinued (Refer to Product Affected Section, Group 3).**

Texas Instruments, Incorporated (TI) is announcing the discontinuance of select devices sourced in the Dongbu foundry. A life time buy is being offered per the date show above. Recommended replacements are also offered on some devices as shown in the Product Affected Section.

NOTE: There are no samples offered for withdrawn/obsolete products. For samples of any replacement products, please contact your local sales representative.

Reason for Withdrawal/Discontinuance:

Dongbu is discontinuing technologies used to make these devices

Product Affected:

Group 1: Reinstates Selected Devices to Active Status

SN65LV1023ADB	SN65LV1224BDB	SN65LV1224BRHBRG4	TLK1221RHAR
SN65LV1023ADBG4	SN65LV1224BDBG4	SN65LV1224BRHBT	TLK1221RHARG4
SN65LV1023ADBR	SN65LV1224BDBR	SN65LV1224BRHBTG4	TLK1221RHAT
SN65LV1023ARHBR	SN65LV1224BDBRG4	TLK1211RCP	TLK1221RHATG4
SN65LV1023ARHBT	SN65LV1224BRHBR	TLK1211RCPG4	

Group 2: Adds Selected Devices to Discontinuance Notification

Product Being Discontinued	RECOMMENDED REPLACEMENT PRODUCTS	REPLACEMENT CODES
TL16C752BPTG4	TL16C752DPFBR	P
TL16C752BPTRG4	TL16C752DPFBR	P

Replacement Notes:

F = Similar functionality but not equivalent.

P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.

Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.

S = EXACT equivalent in functionality and parametrically to the compared device.

Group 3: Corrects Recommended Replacement Products

Product Being Discontinued	RECOMMENDED REPLACEMENT PRODUCTS	REPLACEMENT CODES
TAS5001PFB	TAS5086DBT/TAS5558DCA	F
TAS5001PFBR	TAS5086DBT/TAS5558DCA	F
TAS5001PFBRG4	TAS5086DBT/TAS5558DCA	F
TAS5010IPFB	TAS5086DBT/TAS5558DCA	F
TAS5010IPFBG4	TAS5086DBT/TAS5558DCA	F
TAS5010PFB	TAS5086DBT/TAS5558DCA	F
TAS5010PFBR	TAS5086DBT/TAS5558DCA	F
TAS5012IPFB	TAS5086DBT/TAS5558DCA	F
TAS5012PFB	TAS5086DBT/TAS5558DCA	F
TAS5012PFBRG4	TAS5086DBT/TAS5558DCA	F
TAS5012PFBR	TAS5086DBT/TAS5558DCA	F
TAS5076PFC	TAS5086DBT/TAS5558DCA	F
TAS5076PFCG4	TAS5086DBT/TAS5558DCA	F

Replacement Notes:

F = Similar functionality but not equivalent.

P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.

Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.

S = EXACT equivalent in functionality and parametrically to the compared device.

Updated Consolidated Product Affected Section:

Product Being Discontinued	RECOMMENED REPLACEMENT PRODUCTS	REPLACEMENT CODES
CDCV857DGG	CDCV857BDGG	Q
CDCV857DGGG4	CDCV857BDGG	Q
CDCV857DGGGR	CDCV857BDGGR	Q
CDCV857DGGGRG4	CDCV857BDGGR	Q
SLK2511CPZP	None	Not Applicable
SLK2511IPZP	None	Not Applicable
SLK2721IPZP	None	Not Applicable
SN65LV1021DB	DS92LV1021AMSA	Q
SN65LV1021DBG4	DS92LV1021AMSA	Q
SN65LV1021DBR	DS92LV1021AMSA	Q
SN65LV1021DBRG4	DS92LV1021AMSA	Q
SN65LV1023ADB	SN65LVDS93DGG	F
SN65LV1023ADBG4	SN65LVDS93DGG	F
SN65LV1023ADBR	SN65LVDS93DGG	F
SN65LV1023ARHBR	SN65LVDS93DGG	F
SN65LV1023ARHBT	SN65LVDS93DGG	F
SN65LV1023DB	SN65LVDS93DGG	F
SN65LV1224BDB	DS92LV1224TMSA	Q
SN65LV1224BDBG4	DS92LV1224TMSA	Q
SN65LV1224BDBR	DS92LV1224TMSA	Q
SN65LV1224BDBRG4	DS92LV1224TMSA	Q
SN65LV1224BRHBR	DS92LV1224TMSA	Q
SN65LV1224BRHBRG4	DS92LV1224TMSA	Q
SN65LV1224BRHBT	DS92LV1224TMSA	Q
SN65LV1224BRHBTG4	DS92LV1224TMSA	Q
TAS5001PFB	TAS5086DBT/TAS5558DCA	F
TAS5001PFBR	TAS5086DBT/TAS5558DCA	F
TAS5001PFBRG4	TAS5086DBT/TAS5558DCA	F
TAS5010IPFB	TAS5086DBT/TAS5558DCA	F
TAS5010IPFBG4	TAS5086DBT/TAS5558DCA	F
TAS5010PFB	TAS5086DBT/TAS5558DCA	F
TAS5010PFBR	TAS5086DBT/TAS5558DCA	F
TAS5012IPFB	TAS5086DBT/TAS5558DCA	F
TAS5012PFB	TAS5086DBT/TAS5558DCA	F
TAS5012PFBG4	TAS5086DBT/TAS5558DCA	F
TAS5012PFBR	TAS5086DBT/TAS5558DCA	F
TAS5076PFC	TAS5086DBT/TAS5558DCA	F
TAS5076PFCG4	TAS5086DBT/TAS5558DCA	F
TAS5725RGZR	None	Not Applicable
TAS5725RGZT	None	Not Applicable
TL16C752BPT	TL16C752DPFBR	P

TL16C752BPTG4	TL16C752DPFBR	P
TL16C752BPTR	TL16C752DPFBR	P
TL16C752BPTRG4	TL16C752DPFBR	P
TLC320AD77CDB	TLV320AIC3104IRHBT	F
TLC320AD77CDBG4	TLV320AIC3104IRHBT	F
TLC320AD77CDBR	TLV320AIC3104IRHBR	F
TLK1201AIRCPC	TLK2201BIRCP	F
TLK1201AIRCPCG4	TLK2201BIRCP	F
TLK1201AIRCPCR	TLK2201BIRCPCR	F
TLK1201AIRCPCRG4	TLK2201BIRCPCR	F
TLK1201ARCP	TLK2201BRCP	F
TLK1201ARCPG4	TLK2201BRCP	F
TLK1201ARCPR	TLK2201BRCPR	F
TLK1201ARCPRG4	TLK2201BRCPR	F
TLK1201IRCP	TLK2201BIRCP	F
TLK1201IRCPCR	TLK2201BIRCPCR	F
TLK1201RCP	TLK2201BRCP	F
TLK1211RCP	TLK2201BIRCP	F
TLK1211RCPG4	TLK2201BIRCP	F
TLK1221RHAR	TLK2201BIRCP	F
TLK1221RHARG4	TLK2201BIRCP	F
TLK1221RHAT	TLK2201BIRCP	F
TLK1221RHATG4	TLK2201BIRCP	F
TLK1521IPAP	TLK1501IRCP	F
TLK1521IPAPG4	TLK1501IRCP	F
TLK2201AJRGQE	TLK2201BIRCP	F
TLK2201AJRZQE	TLK2201BIRCP	F
TLK2201IRCP	TLK2201BIRCP	F
TLK2201JRGQE	TLK2201BIRCP	F
TLK2201RCP	TLK2201BIRCP	F
TLK2201RCPCR	TLK2201BIRCPCR	F
TLK2211RCP	TLK2201BIRCP	F
TLK2211RCPCR	TLK2201BIRCPCR	F
TLK2211RCPCRG4	TLK2201BIRCP	F
TLK2218ZPV	TLK2226ZEA	F
TLK2521IPAP	TLK2501IRCP	F
TLK2521IPAPG4	TLK2501IRCP	F
TLK2541PFP	TLK2501IRCP	F
TLK2541PFPG4	TLK2501IRCP	F
TLK2541PFPR	TLK2501IRCP	F
TLK2541PFPRG4	TLK2501IRCP	F
TLK2701IRCP	TLK2501IRCP	F
TLK2701IRCPG4	TLK2501IRCP	F
TLK2701IRCPCR	TLK2501IRCPCR	F

TLK2701IRCPRG4	TLK2501IRCPR	F
TLK2711AIRCPC	TLK2501IRCPC	F
TLK2711AIRCPR	TLK2501IRCPC	F
TLK2711IRCPC	TLK2501IRCPC	F
TLK2711IRCPG4	TLK2501IRCPC	F
TLK3101IRCPC	TLK2501IRCPC	F
TLK3101IRCPG4	TLK2501IRCPC	F
TLK3114SCGPV	TLK10034AAJ	F
TLK4015IGPV	TLK1501IRCPC	F
TLK4015IZPV	TLK1501IRCPC	F
TLK4120IZPV	TLK3134ZEL	F
TLV320AIC3006IZQER	None	Not Applicable
TLV320AIC37IZQER	None	Not Applicable
TLV320DAC33BNIZQCR	None	Not Applicable
TLV320DAC33BNIZQCT	None	Not Applicable
TLV320DAC33NIZQCR	None	Not Applicable
TUSB5052PZ	TUSB3410VF	F
TWL93017EZPHR	None	Not Applicable

Replacement Notes:

F = Similar functionality but not equivalent.

P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.

Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.

S = EXACT equivalent in functionality and parametrically to the compared device.

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com