



Product Discontinuance Notice - PDN 15_0057 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

ADL5322 and ADL5323 Obsolescence

Publication Date: 26-Jun-2015

Last Time Buy Date: 26-Jun-2016

Last Time Ship Date: 26-Jun-2017

Revision Description:

Initial Release

Reason For Discontinuance

ADI is discontinuing these products due to decreased customer demand.

Comments

The ADL5322 and ADL5323 are 3mm x 3mm 8L LFCSP.
Replacement product is ADL5324 offered in a SOT-89 package.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com	Europe: PDN_Europe@analog.com	Japan: PDN_Japan@analog.com
		Rest of Asia: PDN_ROA@analog.com

PDN 15_0057 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
ADL5322ACPZ-R2	ADL5322	ADL5324ARKZ-R7	no	
ADL5322ACPZ-R7	ADL5322	ADL5324ARKZ-R7	no	
ADL5322ACPZ-WP	ADL5322	ADL5324ARKZ-R7	no	
ADL5323ACPZ-R2	ADL5323	ADL5324ARKZ-R7	no	
ADL5323ACPZ-R7	ADL5323	ADL5324ARKZ-R7	no	

Appendix A - PDN 15_0057 Revision History

Rev	Publish Date	Rev Description
Rev. -	26-Jun-2015	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:905 Layout Rev:2 Parent DocId:None