

Micron Technology, Inc. 8000 S. Federal Way PO Box 6 Boise, ID United States

EOL Specific SLC NAND Parts With Low Usage

PCN: 32224

Published: 2017-02-17 Revision History:

Revision 2, 2017-09-22: This document supersedes the original PCN #32224, dated 2017-02-17 and Revision dated 2017-04-05.

Update replacement part for MT29F4G08ABAEAH4-IT:E and remove MT29F4G08ABBEAH4-IT:E from the Affected Micron Part Number List.

Revision 1, 2017-04-05: This document supersedes the original PCN #32224, dated 2017-02-17.

Update to the Affected Micron Part List — MT29F4G16ABBEAM70M3WC1 is being removed.

Updates have also been made to several replacement part numbers.

Type:	End of Life
Description:	Micron will EOL specific NAND MPNs listed that have either no usage or no longer meet customer requirements. The list includes all parts of the DID M79M and a few parts that belong to DIDs M68A, M69A, M60A, M70M and M71M. Please use the replacement part guidance as a first level of recommendation or reach out to your Micron contact for further assistance.

Affected Micron Part Number	Recommended Replace
MT29F4G08ABBDAHC:D	MT29F4G08ABBDAHC-IT:D
MT29F4G16ABBDAHC:D	MT29F4G16ABBDAHC-IT:D
MT29F8G08ADBDAH4:D	MT29F4G08ABBDAH4-AITX:
MT29F8G16ADADAH4:D	MT29F8G16ADADAH4-IT:D
MT29F4G01AAADDHC:D	MT29F4G01AAADDHC-ITX:E
MT29F4G01AAADDHC-IT:D	MT29F4G01AAADDHC-ITX:
MT29F2G01AAAEDH4:E	MT29F2G01AAAEDH4-ITX:E
MT29F2G16ABBEAHC:E	Contact Factory
MT29F1G08ABBDAHC:D	Contact Factory
MT29F1G16ABBDAH4:D	MT29F1G16ABBEAH4:E
MT29F8G16ABBCAM71M3WC1	Contact Factory
MT29F16G08ADBCAH4-IT:C	MT29F16G08ABCCBH1-10IT
MT29F8G16ABBCAH4-IT:C	MT29F8G16ADBDAH4-IT:D
MT29F8G16ABBCAH4:C	MT29F8G16ADBDAH4-IT:D
MT29F16G16ADBCAH4:C	Contact Factory
MT29F16G16ADBCAH4-IT:C	Contact Factory
MT29F8G16ABACAWP:C	MT29F8G16ABACAWP-IT:C
MT29F8G16ABACAH4:C	Contact Factory
MT29F16G08ADACAH4:C	Contact Factory
MT29F16G16ADACAH4:C	Contact Factory
MT29F16G16ADACAH4-IT:C	Contact Factory
MT29F8G16ABACAH4-IT:C	Contact Factory
MT29F16G08ADACAH4-IT:C	MT29F16G08ABCCBH1-10IT
MT29F4G16ABAEAWP:E	MT29F4G16ABADAWP:D
MT29F4G16ABBEAH4:E	MT29F4G16ABBDAH4:D
MT29F4G16ABAEAH4-IT:E	MT29F4G16ABADAH4-IT:D
MT29F4G08ABAEAH4-IT:E	MT29F4G08ABAEAH4-ITS:E
MT29F4G16ABBEAH4-IT:E	MT29F4G16ABBDAH4-IT:D
MT29F2G08ABAEAH4-E:E	Contact Factory
MT29F8G08ADADAH4-E:D	Contact Factory
MT29F1G08ABADAH4-ITE:D	MT29F1G08ABAFAH4-ITE:F
MT29F1G08ABBEAH4:E	MT29F1G08ABBEAH4-IT:E
MT29F1G16ABBEAHC:E	MT29F1G16ABBEAH4:E
MT29F4G08ABAEAH4-S:E	MT29F4G08ABAEAH4:E
MT29F8G08ABACAH4-S:C	MT29F8G08ABACAH4:C
MT29F4G08ABADAM60A3WC1	Contact Factory
MT29F2G16ABBFAH4:F	Contact Factory
MT29F2G16ABBFAH4-IT:F	Contact Factory
MT29F2G16ABAFAWP:F	MT29F2G08ABAGAWP-IT:G
MT29F2G08ABBFAH4:F	MT29F2G08ABBGAH4-IT:G
MT29F2G08ABBFAH4-IT:F	MT29F2G08ABBGAH4-IT:G
MT29F2G08ABAFAH4-ITS:F	MT29F2G08ABAGAH4-IT:G
MT29F2G08ABAFAWP:F	MT29F2G08ABAGAWP-IT:G

Manufacturing Efficiency Reason:

Product Affected: All M79M parts, and a few parts that belong to the DIDs M68A, M69A, M60A, M70M and M71M

Affected Micron Part Number	Recommended Replacement	Customer Part Number
Component		
MT29F16G08ADACAH4:C	Contact Factory	
MT29F16G08ADACAH4-IT:C	MT29F16G08ABCCBH1- 10ITZ:C	
MT29F16G08ADBCAH4-IT:C	MT29F16G08ABCCBH1- 10ITZ:C	
MT29F16G16ADACAH4:C	Contact Factory	
MT29F16G16ADACAH4-IT:C	Contact Factory	
MT29F16G16ADBCAH4:C	Contact Factory	
MT29F16G16ADBCAH4-IT:C	Contact Factory	
MT29F1G08ABADAH4-ITE:D	MT29F1G08ABAFAH4- ITE:F	
MT29F1G08ABBDAHC:D	Contact Factory	557-1485-2-ND
MT29F1G08ABBEAH4:E	MT29F1G08ABBEAH4- IT:E	
MT29F1G16ABBDAH4:D	MT29F1G16ABBEAH4:E	
MT29F1G16ABBEAHC:E	MT29F1G16ABBEAH4:E	
MT29F2G01AAAEDH4:E	MT29F2G01AAAEDH4- ITX:E	
MT29F2G08ABAEAH4-E:E	Contact Factory	
MT29F2G08ABAFAH4:F	MT29F2G08ABAGAH4- IT:G	
MT29F2G08ABAFAH4-IT:F	MT29F2G08ABAGAH4- IT:G	
MT29F2G08ABAFAH4-ITS:F	MT29F2G08ABAGAH4- IT:G	
MT29F2G08ABAFAH4-S:F	MT29F2G08ABAGAH4- IT:G	
MT29F2G08ABAFAWP:F	MT29F2G08ABAGAWP- IT:G	
MT29F2G08ABAFAWP-IT:F	MT29F2G08ABAGAWP- IT:G	
MT29F2G08ABBFAH4:F	MT29F2G08ABBGAH4- IT:G	
MT29F2G08ABBFAH4-IT:F	MT29F2G08ABBGAH4-	

IT:G

	11:G	
MT29F2G16ABAFAWP:F	MT29F2G08ABAGAWP- IT:G	
MT29F2G16ABBEAHC:E	Contact Factory	
MT29F2G16ABBFAH4:F	Contact Factory	
MT29F2G16ABBFAH4-IT:F	Contact Factory	
MT29F4G01AAADDHC:D	MT29F4G01AAADDHC- ITX:D	
MT29F4G01AAADDHC-IT:D	MT29F4G01AAADDHC-ITX:D	
MT29F4G08ABAEAH4-IT:E	MT29F4G08ABAEAH4- ITS:E	557-1672-2-ND
MT29F4G08ABAEAH4-S:E	MT29F4G08ABAEAH4:E	
MT29F4G08ABBDAHC:D	MT29F4G08ABBDAHC- IT:D	
MT29F4G16ABAEAH4-IT:E	MT29F4G16ABADAH4- IT:D	
MT29F4G16ABAEAWP:E	MT29F4G16ABADAWP:D	
MT29F4G16ABBDAHC:D	MT29F4G16ABBDAHC- IT:D	557-1463-2-ND
MT29F4G16ABBEAH4:E	MT29F4G16ABBDAH4:D	
MT29F4G16ABBEAH4-IT:E	MT29F4G16ABBDAH4- IT:D	
MT29F8G08ABACAH4-S:C	MT29F8G08ABACAH4:C	
MT29F8G08ADADAH4-E:D	Contact Factory	
MT29F8G08ADBDAH4:D	MT29F4G08ABBDAH4- AITX:D	
MT29F8G16ABACAH4:C	Contact Factory	
MT29F8G16ABACAH4-IT:C	Contact Factory	
MT29F8G16ABACAWP:C	MT29F8G16ABACAWP- IT:C	MT29F8G16ABACAWP:C-ND
MT29F8G16ABBCAH4:C	MT29F8G16ADBDAH4- IT:D	557-1680-2-ND
MT29F8G16ABBCAH4-IT:C	MT29F8G16ADBDAH4- IT:D	
MT29F8G16ADADAH4:D	MT29F8G16ADADAH4- IT:D	
Wafer		
MT29F4G08ABADAM60A3WC1	Contact Factory	
MT29F8G16ABBCAM71M3WC1	Contact Factory	

*Materials that have been ordered are in **bold**.

Method of Identification:	Marketing Part Number
Micron Sites Affected:	All Sites
Last Purchase Date*:	2017-08-17
Last Shipment Date:	2018-02-17

^{*}Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Thank you

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.