

PRODUCT CHANGE NOTIFICATION

Ref Nr: PCN-20220105002

Date: Jan. 5th , 2022

TO: ALL CUSTOMERS (with appendix)**FROM:** SBU Global Field Marketing**HEREWITH YOU ARE INFORMED OF OUR INTENTION TO CHANGE YAGEO BRANDING TO PULSE****DESCRIPTION:**

YAGEO Corp. hereby announce that Inductor Branding will change from YAGEO to PULSE.

- 3 months phase in is defined. The PCN effective date is 2022/01/05 and all affected part numbers will be remained. No change.
- In the interim, customers can place order either via YAGEO or PULSE channel.
- From 2022/04/01, all the inductor order will be taken by PULSE channel only.
- There is no change to the manufacturing location, processes, materials, equipment and personnel (anything that could affect fit, form and function of the product).

For detail, please contact local YAGEO/PULSE Sales representative.

REASONS:

Global branding name of Inductor is utilized with the intention of managing product lines more consistent.

EXPECTED INFLUENCE ON PERFORMANCE: No change**EXPECTED INFLUENCE ON QUALITY AND RELIABILITY:** No change**FOR MORE INFORMATION, CONTACT:** Algo.lin@yageo.com**RETURN YOUR COMMENTS BEFORE:** Feb. 15 ,2022**Remarks:** If you have no comment before Feb 15, 2022, we will trust as you can accept this brand change.**Comments:****Date:****Function:****Signature:**

Appendix: The YAGEO/PULSE inductor series list (see page 2)

YAGEO = PULSE			
Inductor Series	Inductor Series	Inductor Series	Inductor Series
ABPY001608xxxxxxxxxx	BMRA000606xxxxxxxxxx	NLC3225xxxxxxxxxxxxxx	SL1012xxxxxxxxxxxxxx
AWCU002012xxxxxxxxxx	BMRF001010xxxxxxxxxx	NLC4532xxxxxxxxxxxxxx	SL1016Txxxxxxxxxxxxxx
AWCU004532xxxxxxxxxx	BPSD000807xxxxxxxxxx	NLC5650xxxxxxxxxxxxxx	SLF1045xxxxxxxxxxxxxx
AWVS005050xxxxxxxxxx	BSCH000603xxxxxxxxxx	PBJ2012xxxxxxxxxxxxxx	SLF1275xxxxxxxxxxxxxx
AWVS006060xxxxxxxxxx	BSCH001005xxxxxxxxxx	PBY1005xxxxxxxxxxxxxx	SQC4532xxxxxxxxxxxxxx
AWVT003030xxxxxxxxxx	BSCH001608xxxxxxxxxx	PBY1608xxxxxxxxxxxxxx	SQC5750xxxxxxxxxxxxxx
BBBK001608xxxxxxxxxx	BSCQ000603xxxxxxxxxx	PBY2012xxxxxxxxxxxxxx	SQV4532xxxxxxxxxxxxxx
BBBK002012xxxxxxxxxx	BWCS001610xxxxxxxxxx	PBY3216xxxxxxxxxxxxxx	SSL0402xxxxxxxxxxxxxx
BBGK001608xxxxxxxxxx	BWCS002317xxxxxxxxxx	RH03506xxxxxxxxxxxxxx	SSL0503xxxxxxxxxxxxxx
BBGK002012xxxxxxxxxx	BWVF002520xxxxxxxxxx	SBK1608xxxxxxxxxxxxxx	SSL0802xxxxxxxxxxxxxx
BBHV001608xxxxxxxxxx	BWVF003030xxxxxxxxxx	SBK2012xxxxxxxxxxxxxx	SSL0804xxxxxxxxxxxxxx
BBNQ001608xxxxxxxxxx	BWVS004040xxxxxxxxxx	SBK3216xxxxxxxxxxxxxx	SSL0810xxxxxxxxxxxxxx
BBPY001005xxxxxxxxxx	BWVS005050xxxxxxxxxx	SBY1005xxxxxxxxxxxxxx	TC3220xxxxxxxxxxxxxx
BBPY001608xxxxxxxxxx	BWVS006060xxxxxxxxxx	SBY2012xxxxxxxxxxxxxx	UPB2012xxxxxxxxxxxxxx
BBPY002012xxxxxxxxxx	BWVS008080xxxxxxxxxx	SCD0302xxxxxxxxxxxxxx	UPB3216xxxxxxxxxxxxxx
BBPY003216xxxxxxxxxx	CL1608xxxxxxxxxxxxxx	SCD0403xxxxxxxxxxxxxx	
BBSY001005xxxxxxxxxx	CL2012xxxxxxxxxxxxxx	SCD0503xxxxxxxxxxxxxx	
BBUP001608xxxxxxxxxx	CLH0603xxxxxxxxxxxxxx	SCD0504xxxxxxxxxxxxxx	
BBUP002012xxxxxxxxxx	CLH1608xxxxxxxxxxxxxx	SCD0705xxxxxxxxxxxxxx	
BBUP003216xxxxxxxxxx	GBK1608xxxxxxxxxxxxxx	SCD1005xxxxxxxxxxxxxx	
BDGD002016xxxxxxxxxx	GBK2012xxxxxxxxxxxxxx	SCDS125xxxxxxxxxxxxxx	
BDHE002016xxxxxxxxxx	HFJ1005xxxxxxxxxxxxxx	SCDS127xxxxxxxxxxxxxx	
BDHE002520xxxxxxxxxx	LVF3030xxxxxxxxxxxxxx	SCDS74Txxxxxxxxxxxxxx	
BKP002012xxxxxxxxxx	MHCC06xxxxxxxxxxxxxx	SDS0402xxxxxxxxxxxxxx	
BMQA000606xxxxxxxxxx	NL2520xxxxxxxxxxxxxx	SDT0804xxxxxxxxxxxxxx	
BMRA000404xxxxxxxxxx	NL3225xxxxxxxxxxxxxx	SL0608Txxxxxxxxxxxxxx	
BMRA000505xxxxxxxxxx	NL4532xxxxxxxxxxxxxx	SL0810Txxxxxxxxxxxxxx	