
PRODUCT CHANGE NOTICE

Product Improvement – Design Change for Intersil ISL6308A* Products

**Refer to:
PCN13039**

Date: June 26, 2013

June 26, 2013

To: Our Valued Intersil Customer

Subject: **Product Improvement** – Design Change for Intersil ISL6308A* Products

This notice is to inform you that Intersil has made minor revisions to a single mask level for select ISL6308A* products. The mask modifications result in the fuse trim bits being hard coded to better center the trim parameters without the blowing of the trim fuse(s). The software used for package level electrical test has been updated to discontinue the use of the fuse trim algorithm.

These minor changes will not affect the form, fit, function, or interchangeability of product. The *trim-free* parts shall continue to meet the current data sheet specification and are completely compatible in any existing designs using the trimmed version of the product. There will be no change in the external marking of the packaged parts. Parts affected by this change are identifiable via Intersil's internal traceability system.

Products affected: **ISL6308ACRZ ISL6308ACRZ-T ISL6308AIRZ ISL6308AIRZ-T ISL6308AIRZ-TS2705**

Intersil will take all necessary actions to conform to agreed upon customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to receive product fabricated using the *trim-free* design beginning ninety days from the date of this notice or upon depletion of existing material.

If you have concerns with this notice, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,



Jeff Touvell
Intersil Corporation

PCN13039

CC: J. McNamara F. Elia D. Decrosta J. Zhai T. Huynh D. Yim