



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000863

DATE: 24-Oct-2017

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	DS3905U-020+	N/A			Part reactivated from prior notice: M000847
Reactivation	DS3905U-020+T&R	N/A			Part reactivated from prior notice: M000847
Reactivation	DS4424EVKIT#	N/A			Part reactivated from prior notice: M0009071
Reactivation	MAX5714AUD+	N/A			Part reactivated from prior notice: M000859
Reactivation	MAX5714AUD+T	N/A			Part reactivated from prior notice: M000858
Reactivation	MAX5715AAUD+	N/A			Part reactivated from prior notice: M000859
Reactivation	MAX5715AAUD+T	N/A			Part reactivated from prior notice: M000859
Reactivation	MAX9140AAXK/V+	N/A			Part reactivated from prior notice: M000849
Reactivation	SD417+	N/A			Part reactivated from prior notice: M000843
Reactivation	SD417+T	N/A			Part reactivated from prior notice: M000843
Discontinuance	DSSHA2DEMOKIT#	N/A	24-Oct-2017	24-Oct-2017	EVKIT is No Longer Supported
Discontinuance	MAX32600-KIT-W#	N/A	24-Oct-2017	24-Oct-2017	EVKIT is No Longer Supported

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 24-Nov-2017