



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000768

DATE: 04-Oct-13

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS2251T-128-16	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2251T-128-16#	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2251T-32-16	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2251T-32-16#	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2251T-64-16	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2251T-64-16#	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2252T-128-16	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2252T-128-16#	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2252T-32-16	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2252T-32-16#	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2252T-64-16	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2252T-64-16#	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2253T-128-16	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2253T-32-12	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2253T-32-16	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2253T-612	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2401AX1-02C-126	DS2401P+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2401AX1-02F-4D43/SAFT	DS2401P+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2401AX1-03A-A02	DS2401P+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2401AX1-03B-00	DS2401P+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2401AX1-102-0D2	DS2401P+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2401AX1-102-0D2#	DS2401P+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2401AX1-109-61#T	DS2401P+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2401X1	DS2401P+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2401X1#U	DS2401P+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2401X1-115-A4B#T	DS2401P+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2401X1-S#T	DS2401P+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2411X	DS2411R+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS2411X#U	DS2411R+T&R	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured

Discontinuance	DS80C400-FNY+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS80C410-FNY+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	DS80C411-FNY+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1506XETL+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1526ETM	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1526ETM+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1526ETM+C2M	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1526ETM+G104	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1526ETM+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1526ETM+TDG104	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1526ETM+TG104	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1526ETM+TGA8	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1526ETM-G104	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1802EHJ	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1802EHJ+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1802EHJ+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1827ETL+TG104	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1827ETL+TGA8	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1829ETL+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1829ETL+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1829ETL+TW	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX1829ETL+W	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX77612AEMJ+	N/A	4-Oct-2013	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX77663DEWJ+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX77663KEMJ+	N/A	4-Oct-2013	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8594AETG	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8594AETG+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8594ETG	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8594ETG+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8611ETM+TG05	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8611ETM+TGA8	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8616ETL+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8616ETL+CE6	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8616ETL+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8617ETL+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8618ETL+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8621ETG	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8621YETG	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8621YETG+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8621ZETG	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured

Discontinuance	MAX8621ZETG+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8621ZETG+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8671XETL+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8671XETL+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8675EWN+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8675EWN+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8691ETL+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8691ETL+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8691YETL+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8691YETL+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8691YETL+TG104	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8691YETL+TGA8	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8692VETL+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8692XETL+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8692YETL+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8692YETL+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8692YETL+TG104	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8692YETL+TGA8	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8694PEWG+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8694PEWG+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8818AETM+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8818AETM+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8818AETM+TGA8	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8818AEVCMAXQU+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8818BETM+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8818BETM+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8818BETM+TGA8	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8818BEVCMAXQU+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8906EWA+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8906EWA+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8906EWA+TW	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8906EWA+W	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8920BEWI+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8920BEWI+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8920EWI+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8920EWI+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8921EWE+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8921EWE+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8942EWN+	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured
Discontinuance	MAX8942EWN+T	N/A	6-Apr-2014	4-Oct-2015	Part can no longer be manufactured