



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001080I

DATE: 29-Aug-2022

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1088LU-27+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	DS1135LU-12+	DS1135LZ-12+	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	DS1135U-8+	DS1135Z-8+	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	DS2401AX1-109-61+T	DS2401P+T&R	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX11802EWC+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX11802EWC+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX1188BEUP+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX1243BEPA+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX1264BCEG+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX1292ACEG+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX1292ACEG+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX14629EETJ+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX14629EETJ+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX14690DEWX+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX14690DEWX+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX14885EETL+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX14885EETL+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX157BCPA+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX16037PLA29+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX16037PLA29+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX16133LFM+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX16133LFM+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX16133LFM/V+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX16133LFM/V+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX16508GGN+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX16508GGN+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 29-Sep-2022

Discontinuance	MAX16545GPF+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX16545GPF+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX165ACPN+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX17245ETERA+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX17245ETERA+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX17499AAUB+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX17499AAUB+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX17605EVKIT#	N/A	29-Aug-2022	28-Feb-2024	EVKIT is No Longer Supported
Discontinuance	MAX19506EVKIT#	N/A	29-Aug-2022	28-Feb-2024	EVKIT is No Longer Supported
Discontinuance	MAX20070EVKIT#	N/A	29-Aug-2022	28-Feb-2024	EVKIT is No Longer Supported
Discontinuance	MAX2472EVKIT	N/A	29-Aug-2022	28-Feb-2024	EVKIT is No Longer Supported
Discontinuance	MAX2609EVKIT	N/A	29-Aug-2022	28-Feb-2024	EVKIT is No Longer Supported
Discontinuance	MAX317CPA+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX32566-LNJ+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX32566-LNS+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX32566-LNS+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX355EPE+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX4511CPE+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX4529ESA+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX4529ESA+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX4592CUE+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX4592CUE+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX4613EEE+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX4613EEE+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX4748EUD+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX4748EUD+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX5172AEEE+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX5172AEEE+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX5362NEUK+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX5362NEUK+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX5386MEVMINIQU+	N/A	29-Aug-2022	28-Feb-2024	EVKIT is No Longer Supported
Discontinuance	MAX542CCPD+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX5850EVKIT#	N/A	29-Aug-2022	28-Feb-2024	EVKIT is No Longer Supported
Discontinuance	MAX5850EXE+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX5850EXE+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX5863ETM+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 29-Sep-2022

Discontinuance	MAX5880PUXF+C73	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6050BEUR+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6050BEUR+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6314US26D2+CD7	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6384XS46D3+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6384XS46D3+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6423US46+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6423US46+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6457UKD0B+C3G	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6727KAVHD1+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6727KAVHD1+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6791TPSD2+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6791TPSD2+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6805US44D3+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6805US44D3+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6811SEUS+C74356	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6834GXR0+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6834GXR0+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX6977APE+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX739CPD+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX774CPA+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX793SEPE+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX794CPE+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX800MCPE+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX8704EUB+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX8873REUK+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX8873REUK+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX953EUA+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX954EUA+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX954EUA+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MAX96705GTJ/V+TG5H	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MX7524JP+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MX7524JP+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MX7547KCWG+	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	MX7547KCWG+T	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
Discontinuance	VT1196SFQ	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 29-Sep-2022

Discontinuance	VT239WFCX-ADJ	N/A	29-Aug-2022	28-Feb-2024	Part can no longer be manufactured
----------------	---------------	-----	-------------	-------------	------------------------------------